

Newbies

Those wishing to become qualified Edge Protection installers who have **little, or no experience** need to attend the one-day FASET Edge Protection Course. This covers theory & practical work from a MEWP. A Certificate of Attendance is issued and a Trainee card may be applied for at this stage.

After the course the learner needs to log at least 200 hours on site (under supervision) and provide evidence of this in the form of a Portfolio. The Portfolio must cover 6 separate jobs that the learner has installed. This is forwarded to the Trainer for assessment.

This will be followed up by a *Zoom* discussion to go through the contents of the Portfolio.

If the Trainer is satisfied that the learner has demonstrated experience and knowledge, then the learner is signed off and may apply for a 5 year blue CSCS card.

If not, another Portfolio of 3 jobs needs to be submitted, reassessed followed by another Zoom discussion.

Nearly Newbies

PRIOR TO ATTENDING THE COURSE, those with “*some*” experience need to forward videos & pictures from 3 jobs of their Edge Protection work. The Trainer will discuss these with the learner on the day of the course.

If the Trainer is satisfied, the learner will log 100 hours of Edge Protection installation on site (under supervision), and forward a further Portfolio of 3 jobs to the Trainer for assessment. This will be followed up by a Zoom discussion to go through the contents of the Portfolio.

If the Trainer is satisfied that the learner has demonstrated experience and knowledge, then the learner is signed off and may apply for a 5 year blue CSCS card.

If not satisfied, another Portfolio of 3 jobs needs to be submitted and approved prior to being signed off.

Experienced Workers *

Those with “*much*” experience and/or other relevant qualifications, should provide evidence of this to the Trainer. They also need to provide evidence of their work by supplying a portfolio made up from 3 of their jobs. **THIS MUST BE SUPPLIED PRIOR TO ATTENDING THE COURSE.**

If the Trainer is satisfied with the learners performance during the course and the Portfolio, the learner will be signed off. At this point they may apply for a 5 year blue CSCS card (or endorsement on an existing card).

If not satisfied, the learner will need to log a further 100 hours work and then create another Portfolio of 3 jobs and submit this to the Trainer for approval prior to being signed off.

In all cases the Edge Protection course certificate will be annotated “Trainee”.

Course attendance does not guarantee a FASET CSCS card.

Card Renewal

The individual will undertake re-training to ensure their skills are up to date and then the GSA-2 assessment to prove theoretical knowledge and practical skills. The individual renewing must provide their expiring card prior to course attendance. Failure to provide this will result in the individual needing to provide a portfolio in-line with the above for Nearly Newbies & Experienced Learners.

The Portfolio

The Portfolio is a way of demonstrating skills & experience through work on jobs (minimum 6 for new learners). It must be broad, relevant, and clearly the work of the learner. It must include a collection of videos and pictures (that will form the basis of the Zoom discussion). For each job submitted, a Learner Experience Work Record (LEWR) form needs to be completed and supported with RAMS and site induction register.

In all cases, there will be additional charges for individuals NOT meeting portfolio deadlines.